

FOUND AIRCRAFT CANADA INC. SERVICE INSTRUCTION INDEX

S.I. Number	Revision	Date	Description
SI-21-01	0	Aug. 04, 2004	Aft Cabin Air Vents
SI-21-03	0	Nov. 23, 2004	Door Stop Installation, Heater Box
SI-21-06	0	Oct. 17, 2012	Air Conditioner Airflow Improvement
SI-22-01	2	Oct. 29, 2013	S-Tec 55X Autopilot Installation
SI-24-01	0	May 02, 2005	Ignition System Wiring Reconfiguration
SI-24-03	0	Apr. 30, 2008	Main Battery Substitution
SI-25-01	0	Apr. 20, 2005	Optional Rosen Sunvisors
SI-25-02	1	Apr. 25, 2007	Aft Seats Inertia Reel Harness Installation
SI-25-03	0	Apr. 16, 2010	Floor Board Modification
SI-25-05	0	March 12, 2013	Pilot Seat Arm Rest Installation
SI-26-01	1	Nov. 18, 2004	Console Mounted Fire Extinguisher
SI-31-01	1	Sept. 14, 2005	Angled Radios Panel Installation
SI-32-02	0	July 28, 2004	Brake Mount Side Link Replacement
SI-32-03	0	Apr. 28, 2005	Forward Strut Relocation for Aerocet Floats
SI-32-05	2	Apr.25, 2006	Dual Brake Installation Modification
SI-32-06	0	July 17, 2006	Cantilever Step Installation
SI-32-07	0	Sept. 28, 2010	Rebound Puck Replacement
SI-32-08	0	July 14, 2012	4-Hole Pattern Axle – Main Gear Leg
SI-32-09	0	Oct.27, 2012	4-Bolt Axle Retrofit Gear Leg Mod
SI-33-01	0	Oct. 12, 2012	Strobe Light Connections
SI-34-01	0	Dec. 10, 2004	Tracking System Installation
SI-34-02	1	Sept. 29, 2010	Flap Indicator Replacement
SI-53-01	0	Aug. 09, 2004	Rear Seat Track Shim Installation
SI-57-01	2	May 15, 2006	VG/Swept Wing Tip Installation
SI-71-01	0	Aug. 13, 2004	Missing Engine Serial Number Data Plate
SI-79-01	1	Sept. 8, 2005	20 Tube Oil Cooler Retrofit